Error Definition								
Comment s				MARKET MARKET AND THE SECOND				
Time Stamp	2003/12/1 6 10:40	2003/12/1 6 10:42	2003/12/1 6 10:44	2003/12/1 6 10:44	2003/12/1 6 10:51	2003/12/1 6 10:45	2003/12/1 6 10:54	2003/12/1 6 10:55
DBs	USPA T	EPO; JPO; DERW ENT	US-P GPUB	USPA T	USPA T	USPA T	US-P GPUB ; EPO; JPO; DERW ENT; IBM	US-P GPUB ; EPO; JPO; DERW ENT; IBM: TDB
Search Text	fuse\$1 and (terminal\$1 same cooling) and coolant	fuse\$1 and (terminal\$1 same cooling) and coolant	fuse\$1 and (terminal\$1 same cooling) and coolant	fuse\$1 and (terminal\$1 same cooling)	fuse\$1 and (terminal\$1 same cooling same liquid)	9 not 5	fuse\$1 and (terminal\$1 same cooling same liquid)	fuse\$1 and (terminal\$1 and cooling and liquid)
Hits	103	9	20	903	110	96	59	2563
#	1.5	L6	17	18	67	L10	L111	112

0

0

0

0

BRS

ω

Er or rs

Type

BRS

Н

BRS

 \sim

BRS

 \sim

BRS

4

BRS

S

BRS

9

BRS

7

0

0

0

0

	Type	#	Type L # Hits	Search Text	Text	DBs	Time Stamp	Comment	Error Definition	Er ro rs
	BRS	L13 21	21	fuse\$1 same (terminal\$1 and cooling and liquid)		US-P GPUB ; EPO; JPO; DERW ENT; IBM	2003/12/1 6 10:56			
0	.0 BRS L14 75	L14	75	fuse\$1 same (terminal\$1 and cooling and liquid)	and Liquid)	USPA T	USPA 2003/12/1 T 6 10:56			0
1	1 BRS	115 58	58	14 not 10		USPA T	USPA 2003/12/1 T 6 10:56			0